

最高維修費用

Maximum repair cost

Model	Cover Replacment	Parts Replacment	* CMOS Replacment
GFX50S II	HK\$2,800	HK\$8,800	HK\$23,800
GFX100S			
GFX100II			
GFX100S II			
X-S10	HK\$1,800	HK\$3,800	N/A
GF23mmF4 R LM WR	HK\$1,800	HK\$3,800	N/A
GF30mmF3.5 R WR			
GF45mmF2.8 R WR			
GF50mmF3.5 R LM WR			
GF55mmF1.7 R WR			
GF63mmF2.8 R WR			
GF80mmF1.7 R WR			
GF110mmF2 R LM WR			
GF120mmF4 R LM OIS WR MACRO			
GF250mmF4 R LM OIS WR			
GF500mmF5.6 R LM OIS WR			
GF20-35mmF4 R WR			
GF32-64mmF4 R LM WR			
GF35-70mmF4.5-5.6 WR			
GF45-100mmF4 R LM OIS WR			
GF100-200mmF5.6 R LM OIS WR			
XF18-55mmF2.8-4 R LM OIS	HK\$1,000.0	HK\$1,800	N/A
XC15-45mmF3.5-5.6 PZ			

*以上資料只供參考